



6950 East Genesee Street  
 Fayetteville, New York 13066  
 315.455.2714  
 315.455.3022 (fax)  
[info@ellogicny.com](mailto:info@ellogicny.com)  
[www.envirologicny.com](http://www.envirologicny.com)

Monday, January 21, 2019

Lemoyne College Physical Plant  
 1419 Salt Springs Road  
 Syracuse, NY 13214  
 Eric Foertch  
 (315) 445-4500

**Re: Rec Center Lobby: Asbestos Bulk Sample Analysis**

**Project Number: EL19B-53**

**Report Number: 19**

The purpose of this letter is to explain the results of the Polarized Light Microscopy (PLM) and/or Transmission Electron Microscopy (TEM) Asbestos Bulk Sample Analysis that was performed on 1/11/19, 1/16/2019 & 1/17/2019. A total of seven (7) Friable Bulk Sample(s) and ten (10) Non-Friable Organically Bound (NOB) Bulk Sample(s) were analyzed.

| Field ID | Lab ID | Sample Description                              | Asbestos Present? | Analytical Result    | Analysis Performed |
|----------|--------|---|-------------------|----------------------|--------------------|
| JC-1     | 19-149 | Wall Above Soffit by Camera Joint Compound      | No                | No Asbestos Detected | Friable PLM        |
| JC-2     | 19-150 | Wall Above Soffit by Exit Sign Joint Compound   | No                | No Asbestos Detected | Friable PLM        |
| JC-3     | 19-151 | Wall Above Clock Joint Compound                 | No                | No Asbestos Detected | Friable PLM        |
| CT-1     | 19-152 | Above Fire Extinguisher 1x1 Ceiling Tile        | No                | No Asbestos Detected | NOB TEM            |
| CT-2     | 19-153 | Front Vestibule 1x1 Ceiling Tile                | No                | No Asbestos Detected | NOB TEM            |
| PLAS-1   | 19-154 | Front Vestibule - North Column White Plaster    | No                | No Asbestos Detected | Friable PLM        |
| PLAS-2   | 19-155 | Front Vestibule - South Column White Plaster    | No                | No Asbestos Detected | Friable PLM        |
| MAS-1    | 19-156 | Control Room Under Carpet Tan Carpet Mastic     | No                | No Asbestos Detected | NOB TEM            |
| MAS-2    | 19-157 | Secretarial Room Under Carpet Tan Carpet Mastic | No                | No Asbestos Detected | NOB TEM            |
| FT-1     | 19-158 | Under Water Fountain White 12x12 Floor Tile     | No                | No Asbestos Detected | NOB TEM            |
| FT-2     | 19-159 | Under Water Fountain White 12x12 Floor Tile     | No                | No Asbestos Detected | NOB TEM            |
| FTMAS-1  | 19-160 | Under Water Fountain Tile Mastic Under 12x12    | No                | No Asbestos Detected | Friable PLM        |



6950 East Genesee Street  
Fayetteville, New York 13066  
315.455.2714  
315.455.3022 (fax)  
[info@elogenicny.com](mailto:info@elogenicny.com)  
[www.envirologicny.com](http://www.envirologicny.com)

| Field ID | Lab ID | Sample Description                                     | Asbestos Present? | Analytical Result    | Analysis Performed |
|----------|--------|--|-------------------|----------------------|--------------------|
| FTMAS-2  | 19-161 | Under Water Fountain<br>Tile Mastic Under 12x12        | No                | No Asbestos Detected | Friable<br>PLM     |
| CK-1     | 19-162 | Interior on Double Glass Door to Pool<br>Brown Caulk   | No                | No Asbestos Detected | NOB<br>TEM         |
| CK02     | 19-163 | Interior on Glass Door by Fire Panel<br>Brown Caulk    | No                | No Asbestos Detected | NOB<br>TEM         |
| CK-3     | 19-164 | Exterior on North Side of Main Entrance<br>Brown Caulk | No                | No Asbestos Detected | NOB<br>TEM         |
| CK-4     | 19-165 | Exterior on South Side of Main Entrance<br>Brown Caulk | No                | No Asbestos Detected | NOB<br>TEM         |

*As per NYSDOL ICR 56-2.1 (p), an Asbestos Containing Material (ACM) is defined as any material containing greater than one percent (1%) of asbestos, also known as Asbestos Material. ACM is indicated by bold, highlighted and italicized type.*

If you have any additional questions concerning this report, please do not hesitate to call me at 315.455.2714 or email me at [joyce@elogenicny.com](mailto:joyce@elogenicny.com). Thank you.

Sincerely,



Kathleen Joyce  
Technical Director  
Envirologic of New York, Inc.





# Bulk Sample Log / Chain of Custody

EL1913

PROJECT #: EL18B - 53

LAB REPORT #: 19

6950 E. Genesee St. • Fayetteville, New York 13066 • Telephone (315) 455-2714 • Fax (315) 455-3022

WO#

|  |   |                              |
|--|---|------------------------------|
| Project Name/City/Area:<br><b>REC CENTER LOBBY</b> | Client Name: Lemoyne College Physical Plant               | Contact: Eric Foertch        |
| Date: <b>10.9.2019</b>                             | Client Address: 1419 Salt Springs Rd., Syracuse, NY 13214 | Client Phone #: 315-445-4500 |
|  | Hygienist(s): Eric Foertch, CHMM                          | Client Fax #:                |

| Sample Number | Lab ID (lab use only) | Sample Location                | Sample Description      | Sample Type | Condition |
|---------------|-----------------------|--------------------------------|-------------------------|-------------|-----------|
| IC-1          | 19-149                | WALL ABOVE SUFFIT BY CAMERA    | JOINT COMPOUND          |             |           |
| IC-2          | 19-150                | WALL ABOVE SUFFIT BY EXIT SIGN | JOINT COMPOUND          |             |           |
| IC-3          | 19-151                | WALL ABOVE CLOCK               | JOINT COMPOUND          |             |           |
| CT-1          | 19-152                | ABOVE FIRE EXTINGUISHER        | 2X2 CEILING TILE        |             |           |
| CT-2          | 19-153                | FRONT VESTIBULE                | 2X2 CEILING TILE        |             |           |
| PLAS-1        | 19-154                | FRONT VESTIBULE - NORTH COLUMN | PLASTER - WHITE         |             |           |
| PLAS-2        | 19-155                | FRONT VESTIBULE - SOUTH COLUMN | PLASTER - WHITE         |             |           |
| MAS-1         | 19-156                | CONTROL ROOM UNDER CARPET      | CARPET MASTIC - TAN     |             |           |
| MAS-2         | 19-157                | SECRETARIAL ROOM UNDER CARPET  | CARPET MASTIC - TAN     |             |           |
| FT-1          | 19-158                | UNDER WATER FOUNTAIN           | WHITE 12X12 FLOOR TILE  |             |           |
| FT-2          | 19-159                | UNDER WATER FOUNTAIN           | WHITE 12X12 FLOOR TILE  |             |           |
| FTMAS-1       | 19-160                | UNDER WATER FOUNTAIN           | TILE MASTIC UNDER 12X12 |             |           |
| FTMAS-2       | 19-161                | UNDER WATER FOUNTAIN           | TILE MASTIC UNDER 12X12 |             |           |

Sample Type: F = Friable NF = Non-Friable NOB = Non-Friable Organically Bound Condition: I = Intact D = Damaged SD = Significantly Damaged

| Chain of Custody  | Print Name      | Sign, Name             | Date     | Time    |
|---|-----------------|------------------------|----------|---------|
| Sampled By:   | Eric Foertch    | <i>E. Foertch</i>      | 1.9.19   | 1604    |
| Relinquished By:  | ERIC FOERTCH    | <i>E. Foertch</i>      | 1.10.19  | 1233    |
| Received at Lab By:   | Krista M. Davis | <i>Krista M. Davis</i> | 11/10/19 | 1235    |
| Turnaround Time:  | RUSH (Specify): | 24 Hour                | 48 Hour  | 72 Hour |
| IF NO TURNAROUND TIME IS CIRCLED, 5 BUSINESS DAYS WILL BE ASSUMED                   |                 |                        |          |         |
| Please contact the following individual(s) at the following number(s) with results: |                 |                        |          |         |

By signing above, I acknowledge that the data recorded on this form was collected by accurately following bulk sampling procedures outlined in NYS/DOL Industrial Code Rule 56 (12 NYCRR Part 56, Subpart 56-5.1) and all other applicable state and federal regulations.



# Bulk Sample Log / Chain of Custody

6950 E. Genesee St. • Fayetteville, New York 13066 • Telephone (315) 455-2714 • Fax (315) 455-3022

EL19B-

PROJECT #: **EL18B - 53**

LAB REPORT #: 19

WO#

|  |   |                              |
|--|---|------------------------------|
| Project Name/City/Area:<br><b>REC CENTER LOBBY</b> | Client Name: Lemoyne College Physical Plant               | Contact: Eric Foertch        |
| Date: <b>1-9-2019</b>                              | Client Address: 1419 Salt Springs Rd., Syracuse, NY 13214 | Client Phone #: 315-445-4500 |
| Hygienist(s): Eric Foertch, CHMM                   |   | Client Fax #:                |

| Sample Number | Lab ID (lab use only) | Sample Location                       | Sample Description | Sample Type | Condition |
|---------------|-----------------------|---------------------------------------|--------------------|-------------|-----------|
| CK-1          | 19-1162               | INTERIOR ON DOUBLE GLASS DOOR TO POOL | BROWN CAULK        |             |           |
| CK-2          | 19-1163               | INTERIOR ON GLASS DOOR BY FIRE PANEL  | BROWN CAULK        |             |           |
| CK-3          | 19-1164               | EXTERIOR ON NORTH SIDE OF MAIN ENTR   | BROWN CAULK        |             |           |
| CK-4          | 19-1165               | EXTERIOR ON SOUTH SIDE OF MAIN ENTR   | BROWN CAULK        |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |
|               |                       |                                       |                    |             |           |

Sample Type: F = Friable NF = Non-Friable NOB = Non-Friable Organically Bound Condition: I = Intact D = Damaged SD = Significantly Damaged

| Chain of Custody  | Print Name      | Sign Name              | Date    | Time    |
|---|-----------------|------------------------|---------|---------|
| Sampled By:   | Eric Foertch    | <i>E. Foertch</i>      | 1.9.19  | 1622    |
| Relinquished By:  | ERIC FOERTCH    | <i>E. Foertch</i>      | 1.10.19 | 1233    |
| Received at Lab By:   | Krista M. Davis | <i>Krista M. Davis</i> | 1/10/19 | 1235    |
| Turnaround Time:  | RUSH (Specify): | 24 Hour                | 48 Hour | 72 Hour |
| IF NO TURNAROUND TIME IS CIRCLED, 5 BUSINESS DAYS WILL BE ASSUMED |                 |                        |         |         |

▶ Please contact the following individual(s) at the following number(s) with results:

By signing above, I acknowledge that the data recorded on this form was collected by accurately following bulk sampling procedures outlined in NYS/DOL Industrial Code Rule 56 (12 NYCRR Part 56, Subpart 56-5.1) and all other applicable state and federal regulations.



**PLM & TEM BULK ASBESTOS ANALYSIS REPORT**  
**via NYSDOH ELAP Method 198.1, 198.4 and 198.6**

Client: Envirologic of New York, Inc.  
Location: EL19B-53 #19

Job No: 0074-19B  
Page: 1 of 4

Sample Date: 1/9/2019

Sample Received Date: 1/11/2019

| Client ID | Lab ID | Sampling Location                     | Description                   | PLM Asbestos Fibers Type & Percentage | PLM Total Asbestos | NOB | TEM Asbestos Fibers Type & Percentage | TEM Total Asbestos | PLM Non-Asbestos Fibers Type & Percentage | Non-Fibrous Matrix Material % |
|-----------|--------|---------------------------------------|-------------------------------|---------------------------------------|--------------------|-----|---------------------------------------|--------------------|---|-------------------------------|
| CT-1      | 0694   | Above Fire Extinguisher               | White/Gray 2'x2' Ceiling Tile | Inconclusive No Asbestos Detected     | 0%                 | #   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| CT-2      | 0695   | Front Vestibule                       | White/Gray 2'x2' Ceiling Tile | Inconclusive No Asbestos Detected     | 0%                 | #   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| MAS-1     | 0696   | Control Room Under Carpet             | Tan Carpet Mastic             | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| MAS-2     | 0697   | Secretarial Room Under Carpet         | Tan Carpet Mastic             | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| FT-1      | 0698   | Under Water Fountain                  | White 12"x12" Floor Tile      | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| FT-2      | 0699   | Under Water Fountain                  | White 12"x12" Floor Tile      | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| FTMAS-1   | 0700   | Under Water Fountain                  | White/Brown Floor Leveler     | None Detected                         | 0%                 |     | Not Required                          | N/A                | None Detected                             | 100%                          |
| FTMAS-2   | 0701   | Under Water Fountain                  | White/Brown Floor Leveler     | None Detected                         | 0%                 |     | Not Required                          | N/A                | None Detected                             | 100%                          |
| CK-1      | 0702   | Interior on Double Glass Door to Pool | Brown Caulk                   | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                          |
| CK-2      | 0703   | Interior on Glass Door by Fire Panel  | Brown Caulk                   | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                          |

**KEY TO NOB COLUMN SYMBOLS**

No Symbol in the NOB column denotes sample analyzed by ELAP Method 198.1 (PLM).

✓ NOB (non-friable organically bound) denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

⊕ denotes material analyzed by ELAP Method 198.6 (PLM) per NYSDOH. This Method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing greater than 10% vermiculite.

# denotes friable material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

X denotes sample prepped only by ELAP Method 198.6.

\*\* Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

PLM Bulk Asbestos Analysis by New York State Department of Health, ELAP Method 198.1, 198.4 and 198.6 ("Polarized Light Microscopy and Transmission Electron Identifying and Quantitating Asbestos in Bulk Samples and in Non-Friable Organically Bound Bulk Samples.") or EPA 600/M4-82-020 per 40 CFR 763

**ELAP ID No.: 11955**

PLM Date Analyzed: 1/16-17/2019  
PLM Analyst: A. Maciejewski  
Microscope: Olympus BH-2 #241709

TEM Date Analyzed: 1/17/2019  
TEM Analyst: A. Maciejewski  
Microscope: Hitachi 600 AB

**Laboratory Results Approved By:**  
**Asbestos Technical Director or Designee**

Amy Depski

Paradigm Environmental Services, Inc. is not responsible for the data supplied by an independent inspector. New York State Department of Health Environmental Laboratory Program (ELAP) requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This report relates ONLY to the items received by the lab. This report must not be used to claim product endorsement by NYS ELAP or any agency of the U.S. Government. Quality control data (including 95% limits and laboratory or analysts' accuracy and precision) is available upon request.



**PLM & TEM BULK ASBESTOS ANALYSIS REPORT**  
**via NYSDOH ELAP Method 198.1, 198.4 and 198.6**

Client: Envirologic of New York, Inc.  
Location: EL19B-53 #19

Job No: 0074-19B  
Page: 2 of 4

Sample Date: 1/9/2019

Sample Received Date: 1/11/2019

| Client ID | Lab ID | Sampling Location                       | Description | PLM Asbestos Fibers Type & Percentage | PLM Total Asbestos | NOB | TEM Asbestos Fibers Type & Percentage | TEM Total Asbestos | PLM Non-Asbestos Fibers Type & Percentage | Non-Fibrous Matrix % |
|-----------|--------|---|-------------|---------------------------------------|--------------------|-----|---------------------------------------|--------------------|---|----------------------|
| CK-3      | 0704   | Exterior on North Side of Main Entrance | Brown Caulk | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                 |
| CK-4      | 0705   | Exterior on South Side of Main Entrance | Brown Caulk | Inconclusive No Asbestos Detected     | 0%                 | ✓   | None Detected                         | <1.0%              | None Detected                             | 100%                 |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |
|           |        |   |             |                                       |                    |     |                                       |                    |   |                      |

**KEY TO NOB COLUMN SYMBOLS**  
 No Symbol in the NOB column denotes sample analyzed by ELAP Method 198.1 (PLM).  
 ✓ NOB (non-friable organically bound) denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.  
 ♀ denotes material analyzed by ELAP Method 198.6 (PLM) per NYSDOH. This Method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing greater than 10% vermiculite.  
 # denotes friable material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.  
 X denotes sample prepped only by ELAP Method 198.6.  
 \*\* Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.  
 Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

PLM Bulk Asbestos Analysis by New York State Department of Health, ELAP Method 198.1, 198.4 and 198.6 ("Polarized Light Microscopy and Transmission Electron Identifying and Quantitating Asbestos in Bulk Samples and in Non-Friable Organically Bound Bulk Samples.") or EPA 600/M4-62-020 per 40 CFR 763

**ELAP ID No.: 11955**

PLM Date Analyzed: 1/17/2019  
 PLM Analyst: A. Maciejewski  
 Microscope: Olympus BH-2 #241709

TEM Date Analyzed: 1/17/2019  
 TEM Analyst: A. Maciejewski  
 Microscope: Hitachi 600 AB

Laboratory Results Approved By: \_\_\_\_\_  
 Asbestos Technical Director or Designee  
 Amy Dembski

Paradigm Environmental Services, Inc. is not responsible for the data supplied by an independent inspector. New York State Department of Health Environmental Laboratory Program (ELAP) requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This report relates ONLY to the items received by the lab. This report must not be used to claim product endorsement by NYS ELAP or any agency of the U.S. Government. Quality control data (including 95% limits and laboratory or analysts' accuracy and precision) is available upon request.



enviro  
logic  
New York, Inc.

# Bulk Sample Log / Chain of Custody

6950 E. Genesee St. • Fayetteville, New York 13066 • Telephone (315) 455-2714 • Fax (315) 455-5022

0674-19B  
E119B

PROJECT #: E119B - 53  
LAB REPORT #: 19

WO#

|                         |                                 |   |                              |
|-------------------------|---------------------------------|---|------------------------------|
| Project Name/City/Area: | REC CENTER LOBBY                | Client Name: Lemoyne College Physical Plant               | Contact: Eric Foerch         |
| Date: 10.9.2019         | Hygienist(s): Eric Foerch, CHMM | Client Address: 1419 Salt Springs Rd., Syracuse, NY 13214 | Client Phone #: 315-445-4500 |
|                         |                                 |   | Client Fax #:                |

| Sample Number     | Lab ID (lab use only) | Sample Location                | Sample Description               | Sample Type | Condition |
|-------------------|-----------------------|--------------------------------|----------------------------------|-------------|-----------|
| <del>ST-1</del>   |                       | WALL ABOVE SAFETY BY CANEAT    | <del>Form. Contaminants</del>    |             |           |
| <del>TC-2</del>   |                       | WALL ABOVE SAFETY BY EXIT SIGN | <del>Form. Contaminants</del>    |             |           |
| <del>TC-3</del>   |                       | WALL ABOVE GLASS               | <del>Form. Contaminants</del>    |             |           |
| CT-1              | 01094                 | ABOVE FIRE EXTINGUISHER        | 2x2 Ceramic Tile                 |             |           |
| CT-2              | -95                   | FRONT VESTIBULE                | 2x2 Ceramic Tile                 |             |           |
| <del>MAAS-1</del> |                       | FRONT VESTIBULE - NORMA COLUMN | <del>Polystyrene Beadboard</del> |             |           |
| <del>MAAS-2</del> |                       | FRONT VESTIBULE - SANTA COLUMN | <del>Polystyrene Beadboard</del> |             |           |
| MAAS-1            | -96                   | Control Room UNDER CABINET     | Aerobic Mastic - TAN             |             |           |
| MAAS-2            | -97                   | SENDER ROOM UNDER CABINET      | Aerobic Mastic - TAN             |             |           |
| ET-1              | -98                   | UNDER WATER FOUNTAIN           | WHITE 12x12 Floor Tile           |             |           |
| ET-2              | -99                   | UNDER WATER FOUNTAIN           | WHITE 12x12 Floor Tile           |             |           |
| ETMAS-1           | 0700                  | UNDER WATER FOUNTAIN           | Tile Mastic UNDER 12x12          |             |           |
| ETMAS-2           | -01                   | UNDER WATER FOUNTAIN           | Tile Mastic UNDER 12x12          |             |           |

Sample Type: F = Friable NF = Non-Friable NOB = Non-Friable Organically Bound Condition: I = Intact D = Damaged SD = Significantly Damaged

| Chain of Custody    | Print Name      | Signature          | Date     | Time    |
|---------------------|-----------------|--------------------|----------|---------|
| Sampled By:         | Eric Foerch     | <i>[Signature]</i> | 1.9.19   | 1604    |
| Relinquished By:    | ERIC FOERCH     | <i>[Signature]</i> | 1.10.19  | 1233    |
| Received at Lab By: | Krista M. Davis | <i>[Signature]</i> | 11/01/19 | 1235    |
| Turnaround Time:    | RUSH (Specify): | 24 Hour            | 48 Hour  | 72 Hour |

IF NO TURNAROUND TIME IS CIRCLED, 5 BUSINESS DAYS WILL BE ASSUMED

▶ Please contact the following individual(s) at the following number(s) with results:

By signing above, I acknowledge that the data recorded on this form was collected by accurately following bulk sampling procedures outlined in NYS/DOL Industrial Code Rule 56 (12 NYCRR Part 56, Subpart 56-5.1) and all other applicable state and federal regulations.

*Cuprell GZ* 11/11/19 0930 UPS



